OR99E: MP 20.35 – SW BERG PKWY (CANBY)

Building Better Relationships One Project at a Time



SCOPE OF WORK

- Deep Pavement Repair and Restoration of OR99E
- Install Stormwater Improvements
 - Drywells and added drainage facilities over existing storm sewer
- ADA Curb Ramp Improvements and Sidewalk
- Sign and Signal Improvements
- Railroad Crossing Removal and Crossing Upgrade




Existing Storm Sewer System Failure

- Remove and Replace existing Storm Sewer
 - Cause of failing road 60-year-old unreinforced concrete pipe
 - Highway would not hold up another year
- Contract Time
 - Contract Suspended for 6 months
 - 365 Days Added



Existing Road Conditions







Water ponding along mainline

Road failing over existing storm sewer

Deep potholes forming

COMMUNICATION AND INNOVATION

- Communication AND Partnership = Success
 - Railroad
 - Schools
 - Fire Department and Public Services
 - Businesses
 - Canby Fair and other Community Celebrations/Events



COMMUNICATION AND INNOVATION

- Accelerated Construction Schedule
 - Aging road and failing storm line
 - Road condition unable to last additional season
 - ODOT Maintenance and K&E joint effort throughout project potholes
- K&E Proposed Update Traffic Control Plans, ODOT Accepted
 - Signal Shutdown/No Side Street Access for extended periods
 - Increase productivity and decreased time needed to complete project
 - Saved money for both K&E and ODOT








Prior to Repair Lanes in Extremely Poor Repair

Repaired Section of OR99E

TRAFFIC CONTROL

- Contractor Provided/ODOT Approved Traffic Control Plans
- Crossovers with Signal Shutoff
 RR Notification and Testing
- Allowed Multiple Work Areas
- 4773 tons ACP saved
- Increased Work Zone Safety

- Communication Crucial
- Dry Runs with Fire Dept. though work zone
- Flaggers added
- Detours utilized



Original Traffic Control Plan

K&E Provided Traffic Control Plan

NEW STORM SEWER

- Redesign completed by Consultant in 6 months
- K&E assisted in the storm sewer redesign
 - Provided constructability comments during design
 - Additional survey
- Offered Solutions during construction to underground utility conflicts



Pipe Work



Drywell Installation







Inlet

23 drywells at 25' depth

1.3 miles Mainline Storm Sewer 21 PC Manholes 95 Storm MH 78 Inlets 4220' Laterals

5.5" Deep Base Course Lift

- Must be a Fully Contained Area
- Must be Base Course
- Pneumatic Roller used for full depth compaction
- Core Correlation taken
- 10 Additional Cores taken and cut into 3 equal parts for Density Verification throughout mat
 - Top 95.8%, Middle 97.3%, Bottom 96.2%



5.5" Deep Base Lift



Plan Cross Section

Confined Area


Pneumatic Roller used Base allowed to cool overnight

ADA PILOT PROJECT

- Only 2D Plan given to K&E – Only gutter elevation provided
- NO ADA Ramp needed to be removed – Only minor corrections required



ADA Project








Plan Impacted War Memorial and Truck Turning Radius Proposed plan did not impact memorial

Turning Radius adjusted for Truck Exit

RR Replacement Across Hwy 99E

- UPRR, OPRR, Rick Franklin Construction, City of Canby and Fire Dept
- Full Closure started Thursday ended early Sunday Night
 - Schedule and Communication with Railroad Subcontractor





OUTCOMES

- RR Replacement Across Hwy 99E
- 95% ADA Success Rate, 5% minor fixes
- Successful Project
 - Project 98% Completed
 - 2% held up by others
- Great Relationships
- Canby Community Celebration

